

Course 445

Inspection of Particle Control Devices

November 28-30, 2017

AGENDA

LOCATION
Murfreesboro, Tennessee

MODERATOR
J.W. Crowder

DAY & TIME	SUBJECT	SPEAKER
<i>Tuesday, November 28</i>		
8:45	Introduction	J. Crowder
9:00	Pre-Test	
9:30	BREAK	
10:00	Baseline Inspection Technique	J. Crowder
10:30	Inspection of Cyclones	J. Crowder
11:45	LUNCH	
12:45	Inspection of Cyclones (cont'd)	J. Crowder
1:30	Inspection of Fabric Filters	J. Crowder
2:15	BREAK	
2:30	Inspection of Fabric Filters (cont'd)	J. Crowder
4:15	ADJOURN	
<i>Wednesday, November 29</i>		
8:45	Inspection of Fabric Filters (cont'd)	J. Crowder
10:00	BREAK	
10:15	Inspection of Wet Scrubbers	J. Crowder
11:45	LUNCH	
12:45	Inspection of Wet Scrubbers (cont'd)	J. Crowder
2:15	BREAK	
2:30	Inspection of Electrostatic Precipitators	J. Crowder
3:45	Review of Pre-Test	J. Crowder
4:15	ADJOURN	
<i>Thursday, November 30</i>		
8:45	Inspection of Electrostatic Precipitators (cont'd)	J. Crowder
10:15	BREAK	
10:30	Measurement of Inspection Parameters	J. Crowder
11:45	LUNCH	
12:45	Preparation of Flow Charts	J. Crowder
2:00	BREAK	
2:15	Post-Test	
3:15	Course Critique	
3:45	ADJOURN	

Jerry W. Crowder, Ph.D., P.E.
Crowder Environmental Associates, Inc.
120 Cherry Circle
Dyersburg, TN 38024
Tel: 731-286-1554
Fax: 731-286-4910
Cell: 731-589-0911
E-mail: jwcrowder@cableone.net