

# Course 415 Control of Gaseous Emissions

## AGENDA

**LOCATION**  
Frankfort, Kentucky

**MODERATOR**  
J.W. Crowder

DAY & TIME	SUBJECT	SPEAKER
------------	---------	---------

### *Tuesday, August 5*

9:00	Welcome and Registration	J. Crowder
9:15	Pre-Test	
9:45	Introduction to Gaseous Emissions	J. Crowder
10:30	BREAK	
10:45	Control Techniques for Gaseous Contaminants	J. Crowder
11:15	Adsorption	J. Crowder
12:00	LUNCH	
1:00	Adsorption (cont'd)	J. Crowder
2:30	BREAK	
2:45	Adsorption (cont'd)	J. Crowder
3:30	Absorption	J. Crowder
4:30	ADJOURN	

### *Wednesday, August 6*

9:00	Absorption (cont'd)	J. Crowder
10:30	BREAK	
10:45	Absorption (cont'd)	J. Crowder
12:00	LUNCH	
1:00	Absorption (cont'd)	J. Crowder
2:30	BREAK	
2:45	Bioreaction	J. Crowder
3:30	Oxidation	J. Crowder
4:30	ADJOURN	

### *Thursday, August 7*

9:00	Oxidation (cont'd)	J. Crowder
10:30	BREAK	
10:45	Oxidation (cont'd)	J. Crowder
11:30	Condensation	J. Crowder
12:00	LUNCH	

DAY & TIME	SUBJECT	SPEAKER
------------	---------	---------

**Thursday, August 7 (cont'd)**

1:00	Condensation (cont'd)	J. Crowder
2:00	Control Techniques for Nitrogen Oxides	J. Crowder
2:30	BREAK	
2:45	Control Techniques for Nitrogen Oxides (cont'd)	J. Crowder
3:45	Review of Pre-Test	J. Crowder
4:30	ADJOURN	

**Friday, August 8**

9:00	Control of Sulfur Oxides	J. Crowder
10:30	BREAK	
10:45	Control of Greenhouse Gas Emissions	J. Crowder
12:00	LUNCH	
1:00	Post-Test	
2:30	Course Critique	
3:00	ADJOURN	

---

Jerry W. Crowder, Ph.D., P.E.  
 Crowder Environmental Associates, Inc.  
 120 Cherry Circle  
 Dyersburg, Tennessee 38024  
 Tel: 731-286-1554  
 Fax: 731-286-4910  
 Cell: 731-589-0911  
 E-mail: [jwcrowder@cableone.net](mailto:jwcrowder@cableone.net)