

**Course 482**  
**Sources and Control of**  
**Volatile Organic Air Pollutants**

April 24-27, 2018

**AGENDA**

**LOCATION**  
 Nashville, Tennessee

**MODERATOR**  
 J.W. Crowder

DAY & TIME	SUBJECT	SPEAKER
------------	---------	---------

***Tuesday, April 24***

9:00	Welcome and Registration	J. Crowder
9:15	Pre-Test	
9:45	BREAK	
10:00	Properties and Fundamentals	J. Crowder
12:00	LUNCH	
1:00	Properties and Fundamentals (cont'd)	J. Crowder
2:30	BREAK	
2:45	Source Measurement Techniques	J. Crowder
4:30	ADJOURN	

***Wednesday, April 25***

9:00	National Sources and the Regulatory Approach	J. Crowder
10:00	Surface Coating	J. Crowder
10:30	BREAK	
10:45	Surface Coating (cont'd)	J. Crowder
12:00	LUNCH	
1:00	Graphic Arts	J. Crowder
2:30	BREAK	
2:45	Calculating VOC Content of Coatings and Inks	J. Crowder
4:30	ADJOURN	

***Thursday, April 26***

9:00	Oil and Gas Production	J. Crowder
10:00	BREAK	
10:15	Petroleum Refining	J. Crowder
10:45	Petroleum Product Storage and Distribution	J. Crowder
12:00	LUNCH	

DAY & TIME	SUBJECT	SPEAKER
------------	---------	---------

**Thursday, April 26 (cont'd)**

1:00	Petroleum Product Storage and Distribution (cont'd)	J. Crowder
1:30	Degreasing	J. Crowder
2:30	BREAK	
2:45	Dry Cleaning	J. Crowder
3:45	Pre-Test Review	J. Crowder
4:30	ADJOURN	

**Friday, April 27**

9:00	Introduction to Control Technology	J. Crowder
10:15	BREAK	
10:30	Introduction to Control Technology (cont'd)	J. Crowder
12:00	LUNCH	
1:00	Post-Test	
2:30	Course Critique	
3:00	ADJOURN	

---

Jerry W. Crowder, Ph.D., P.E.  
 Crowder Environmental Associates, Inc.  
 120 Cherry Circle  
 Dyersburg, TN 38024-6198  
 Tel: 731-286-1554  
 Fax: 731-286-4910  
 Cell: 731-589-0911  
 E-mail: [jwcrowder@cableone.net](mailto:jwcrowder@cableone.net)