

# Course 413

## Control of Particulate Matter Emissions

June 19-22, 2018

### AGENDA

**LOCATION**  
Columbia, South Carolina

**MODERATOR**  
J.W. Crowder

DAY & TIME	SUBJECT	SPEAKER
------------	---------	---------

#### **Tuesday, June 19**

9:00	Welcome and Registration	J. Crowder
9:30	Pre-Test	
10:00	BREAK	
10:15	Course Overview	J. Crowder
10:30	Review of Basic Concepts	J. Crowder
12:00	LUNCH	
1:00	Particulate Matter Formation and Regulation	J. Crowder
1:45	Particle Sizing	J. Crowder
2:30	BREAK	
2:45	Particle Sizing (cont'd)	J. Crowder
3:30	Particle Collection Mechanisms	J. Crowder
4:30	ADJOURN	

---

*HOMEWORK: Read Chapters 1-4, Student Manual; Review Problems*

---

#### **Wednesday, June 20**

9:00	Particle Collection Mechanisms (cont'd)	J. Crowder
10:00	Settling Chambers	J. Crowder
10:30	BREAK	
10:45	Settling Chambers (cont'd)	J. Crowder
11:00	Cyclones	J. Crowder
12:00	LUNCH	
1:00	Cyclones (cont'd)	J. Crowder
2:30	BREAK	
2:45	Fabric Filters	J. Crowder
4:30	ADJOURN	

---

*HOMEWORK: Read Chapters 5-7, Student Manual; Review Problems*

---

#### **Thursday, June 21**

9:00	Fabric Filters (cont'd)	J. Crowder
10:30	BREAK	
10:45	Wet Scrubbers	J. Crowder
12:00	LUNCH	

DAY & TIME	SUBJECT	SPEAKER
------------	---------	---------

**Thursday, June 21 (cont'd)**

1:00	Wet Scrubbers (cont'd)	J. Crowder
2:30	BREAK	
2:45	Electrostatic Precipitators	J. Crowder
4:00	Pre-Test Review	J. Crowder
4:30	ADJOURN	

---

*HOMEWORK: Read Chapters 8-10, Student Manual; Review Problems*

---

**Friday, June 22**

9:00	Electrostatic Precipitators (cont'd)	J. Crowder
10:30	BREAK	
10:45	Hoods and Fans	J. Crowder
12:00	LUNCH	
1:00	Post-Test	
2:30	Course Critique	
3:00	ADJOURN	

---

Jerry W. Crowder, Ph.D., P.E.  
 Crowder Environmental Associates, Inc.  
 120 Cherry Circle  
 Dyersburg, Tennessee 38024  
 Tel: 731-286-1554  
 Fax: 731-286-4910  
 Cell: 731-589-0911  
 E-mail: [jwcrowder@cableone.net](mailto:jwcrowder@cableone.net)